






I <sub>m</sub>	a		b		c	d	e	f	g	h	j	k	l	m	n	o	p	q	r		s	t	u	v	ø	ø†	N·m	s max. (Cu) mm²				
	3P	4P	3P	4P															Max	Min										h max. l max. (Cu) mm (Cu) mm	z max.	
250A	235		119,5		115,5	25	5,5	157	192	216	45	88	357	170	42	3	67	151	103	7	105	-	133	142	10,5	M10	24	240	31		2x5	30*
315A																																
400A																																
630A	321		162		159	40	7	232	282	312	65	121	482	247	46	5	87	180	75	7	-	245	186	171	12,5	M12	45	2x240	45		2x6	45
800A																																
1000A	424		210		214	50	9	295	375	419	85	163	595	315	57	6	88	208	56	7	-	360	248	199	14,5	M14	55	-	-		2x10	60